

"Quality is our best priority"

A DIFE Enlisted Company

INSPECTION REPORT OF TRUCK MOUNTED CRANE – IQCERT505MLS02

IQCERT / Report / Mahuya Logistics Services / IQCERT35T13						
Owner: Mahuya Logistics Services		Location: 1407, Saraipara,Port Connecting Road, Pahartali, Chattogram		Date of Insp.: 18 MARCH, 2023		
Reff: Mr. Mojaffor H	aider	Designation: Manager-Operation		Date of Exp.:17 MARCH, 2024		
Status/Stu: S= Satisfactory ID=Deficiency N/A= Not Applicable Inspection Classification: ASME B30 & OSHA						
Equipment Type	Truck Mounted Crane		Capacity	35TON		
BRAND NAME	P & H		Chassis No /PIN	NA		
Reg Status	NA		Registration No	NA		
Model	P & H 435TC		Serial Number	MLS-013		
Manufacture Date	UNKNOWN		Rated Power	NA		

#	ITEM	S	ID	NA	Comments
	HISTORICAL DATA				
1	Monthly Inspection Records			\boxtimes	
2	Maintenance Records				
3	Modification Records				
4	Initial & post-repair Load Test Records	\boxtimes			
	GENERAL				
5	Guards / Covers				
6	External Lights				
7	Warning Decals	\boxtimes			
8	Housekeeping	\boxtimes			
9	Hand Signal Chart				
10	No-Load Operational Test	\boxtimes			
	OPERATOR / DRIVER'S CAB				
11	Access - Grab Rails / Steps	\boxtimes			
12	Fire Extinguisher				7 - 1
13	PTO (Power Take Off)	\boxtimes			
14	Parking Brake				
15	Air / Hydraulic Lines	\boxtimes			
16	Instruments / Gauges	\boxtimes			
17	Electrical Switches / Functions	\boxtimes			
18	Hom	\boxtimes			
19	Steering	\boxtimes			
20	Clutch	\boxtimes			
21	Brake	\boxtimes			
22	Operator's manual		\boxtimes		
	POWER GENERATOR (TRUCK OR AUX				
23	Performance	\boxtimes			
24	Exhaust System / Guards & Insulators	\boxtimes			
25	Belts / Hoses	\boxtimes			
26	Guards/Covers - Rot & Recip. Parts	\boxtimes			
	CHASSIS/CARRIER				
27	Transmission	\boxtimes			
28	Driveline	\boxtimes			
29	Tires/Wheels / Chain	\boxtimes			
	1 1 2 3 3 4 4 5 6 6 7 7 8 8 9 10 11 11 12 13 13 14 15 16 17 18 19 20 21 22 22 23 24 25 26 27 28	HISTORICAL DATA 1 Monthly Inspection Records 2 Maintenance Records 3 Modification Records 4 Initial & post-repair Load Test Records GENERAL 5 Guards / Covers 6 External Lights 7 Warning Decals 8 Housekeeping 9 Hand Signal Chart 10 No-Load Operational Test OPERATOR / DRIVER'S CAB 11 Access - Grab Rails / Steps 12 Fire Extinguisher 13 PTO (Power Take Off) 14 Parking Brake 15 Air / Hydraulic Lines 16 Instruments / Gauges 17 Electrical Switches / Functions 18 Hom 19 Steering 20 Clutch 21 Brake 22 Operator's manual POWER GENERATOR (TRUCK OR AUX 23 Performance 24 Exhaust System / Guards & Insulators 25 Belts / Hoses 26 Guards/Covers - Rot & Recip. Parts CHASSIS/CARRIER 27 Transmission 28 Driveline	HISTORICAL DATA 1 Monthly Inspection Records 2 Maintenance Records 3 Modification Records 4 Initial & post-repair Load Test Records GENERAL 5 Guards / Covers 6 External Lights 7 Warning Decals 8 Housekeeping 9 Hand Signal Chart 10 No-Load Operational Test OPERATOR / DRIVER'S CAB 11 Access - Grab Rails / Steps 12 Fire Extinguisher 13 PTO (Power Take Off) 14 Parking Brake 15 Air / Hydraulic Lines 16 Instruments / Gauges 17 Electrical Switches / Functions 18 Hom 19 Steering 20 Clutch 21 Brake 22 Operator's manual POWER GENERATOR (TRUCK OR AUX) 23 Performance 24 Exhaust System / Guards & Insulators 25 Belts / Hoses 26 Guards/Covers - Rot & Recip. Parts CHASSIS/CARRIER 27 Transmission □ ■	HISTORICAL DATA 1 Monthly Inspection Records 2 Maintenance Records 3 Modification Records 4 Initial & post-repair Load Test Records GENERAL 5 Guards / Covers 6 External Lights 7 Warning Decals 8 Housekeeping 9 Hand Signal Chart 10 No-Load Operational Test OPERATOR / DRIVER'S CAB 11 Access - Grab Rails / Steps 12 Fire Extinguisher 13 PTO (Power Take Off) 14 Parking Brake 15 Air / Hydraulic Lines 16 Instruments / Gauges 17 Electrical Switches / Functions 18 Hom 19 Steering 20 Clutch 21 Brake 22 Operator's manual POWER GENERATOR (TRUCK OR AUX 23 Performance 24 Exhaust System / Guards & Insulators 25 Belts / Hoses 26 Guards/Covers - Rot & Recip. Parts 27 Transmission 28 Driveline 28 Driveline	HISTORICAL DATA

Registered Address: Plot #87, BNS Center, Sector #07, Uttara, Dhaka – 1230, Bangladesh

Operation Office: Plot # 03 (3rd Floor), Road # 16, Sector # 11, Uttara Model Town, Dhaka-1230, Bangladesh. Mobile:+8801400-485888, +8801722283001 Email: operation@iqcertinter.com Web: www.iqcertinter.com



"Quality is our best priority"

A DIFE Enlisted Company

INSPECTION REPORT OF TRUCK MOUNTED CRANE – IQCERT505MLS02

			1	 1		
O - PCSA #2 8.3.3.5(3)	30	Tire Air pressure / Roller and Chain Mechanism	\boxtimes			
O - 1926.1412(f)(2)(i)(A)	31	Main Frame Members	\boxtimes			
O - 1926.1412(f)(2)(x)	32	Hydraulic hoses / Tubes / Fittings	\boxtimes			
O - 1926.1412(d)(1)(iv)	33	Hydraulic Fluid Level	\boxtimes			
O - 1926.1423(c)(3)(ii)	34	Anti-Skid Surface	\boxtimes			
O - 1926.601(b)(4)(I)	35	Backup Alarm	\boxtimes			
		OUTRIGGERS / CRAWLER				
O - 1926.1412(f)(2)(i)(A)	36	Beams / Pin	\boxtimes			
A - B30.5-1.9.3(a)	37	Outrigger Lock / Chain pad	\boxtimes			
O - 1926.1412(f)(2)(xiii)	38	Cylinders / Jack	\boxtimes			
O - 1926.1412(f)(2)(xiv)	39	Outrigger Sandpads / Crawler Pad	\boxtimes			
O - 1926.1412(f)(2)(x)	40	Hydraulic Hoses / Tubes / Fittings	\boxtimes			
O - 1926.1412(f)(2)(xii)	41	Holding Valves (Vertical O.R. cylinders)	\boxtimes			
O - 1926.1433(d)(5)	42	Caution / Warning Decals	\boxtimes			
		OPERATOR CONTROLS				
O - 1926.1412(f)(2)(xxi)	43	Grab Rails / Steps / Platforms	\boxtimes			
O - 1926.1423(c)(3)(ii)	44	Anti-Skid Surface	\boxtimes			
O - 1926.1407(g)	45	Electrocution Warning Decal on Remote	\boxtimes			
A - B30.5-1.6.1(b)	46	Fully Operating Remote		\boxtimes		
A - B30.5-1.6.1(a)	47	Controls Identified	\boxtimes			
O - 1926.1412(d)(1)(l)	48	Controls - Forces / Movements / Proportional				
O - PCSA#2 8.2.1.3	49	Hydraulic Leaks	\boxtimes			
O - 1926.1415(a)(7)	50	Horn - Warning Device	\boxtimes			
A - B30.5-1.6.3(a)	51	Remote Start/Stop		\boxtimes		
A - B30.5-1.6.3(b)	52	Speed Control on Remote		\boxtimes		
O - PCSA#2 8.1.4	53	Hydraulic Pressure				
		LOAD CHART				
O - 1926.1433(d)(1)	54	Per Configuration (correct per crane model)				
O - 1910.180(c)(2)	55	Durable				
O - 1910.180(c)(2)	56	Legible				
O - 1926.1417(c)(1)	57	Both Sides of Tower (Visible from Operator's Station)	\boxtimes			
O - 1910.180(c)(2)	58	Securely Attached		\boxtimes	 	
0 1010.100(0)(2)		SAFETY DEVICES/OPERATIONAL AIDE				
O - 1926.1416(e)(1)	59	Boom Angle indicator (both sides)		\boxtimes		
O - 1926.1416(e)(1)	60	Jib Angel Limiter		\boxtimes		
O - 1926.1416(e)(1)	61	Jib / Luffing Adjustment		\boxtimes		
O - 1926.1416(e)(3)	62	Boom length Indicator		П		
O - 1926.1416(e)(4)	63	Overload Protection System	\boxtimes			
O - 1926.1426(b)(4)	64	Counterbalance Valve	\boxtimes			
O - 1926.1415(a)(1)	65	Crane level Indicator	\boxtimes			
O - 1926.1416(d)(3)(I)	66	Anti-2-Block Device				
0 - 1920.1410(u)(3)(1)	00	TOWER/WINCH				
O 1026 1/12/ft/2\/iii\	67	Rotate & Bearing	\boxtimes			
O - 1926.1412(f)(2)(iii)	+					
O - 1926.1412(f)(2)(i)(B)	68	Bolts installed & Torqued (top and bottom)				
O - 1926.1412(f)(2)(x)	69	Hydraulic Hoses / Tubes / Fittings				
O - 1926.1412(f)(2)(xvi)	68	Electric Wiring				
A - B30.5-1.9.11(g)	69	Electrocution Warning Decal				
	-					
		WINCH				
A - B30.5-2.1.3(m)	70	Hydraulic Motors				

Registered Address: Plot # 87, BNS Center, Sector # 07, Uttara, Dhaka – 1230, Bangladesh

Operation Office: Plot # 03 (3rd Floor), Road # 16, Sector # 11, Uttara Model Town, Dhaka-1230, Bangladesh. Mobile:+8801400-485888, +8801722283001 Email: operation@iqcertinter.com Web: www.fqcertinter.com



"Quality is our best priority"

A DIFE Enlisted Company

INSPECTION REPORT OF TRUCK MOUNTED CRANE – IQCERT505MLS02

A - B30.5-1.3.2(2)©	71	Winch - Wrapping on Drum		Ш	Ш	
O - 1926.1413(a)(4)(i)(B)	72	Winch - Minimum Rope Wraps - max ext	\boxtimes			
O - 1926.1433(d)(13)	73	Winch Brake	\boxtimes			
		MAIN BOOM				
O - 1926.1412(f)(2)(xiii)	74	Lift cylinder	\boxtimes			
O - 1926.1412(f)(2)(xiii)	75	Extend Cylinder	\boxtimes			
O - 1926.1412(f)(2)(x)	76	Hydraulic Hoses / Tubes / Fittings	\boxtimes			
O - PCSA #2 4.07.1	77	Boom Section Alignment	\boxtimes			
O - 1926.1412(f)(2)(xv)	78	Wear pads	\boxtimes			
O - 1926.1412(f)(2)(ii)	79	Sheave(s)	\boxtimes			
O - 1926.1413(a)(2)(i)(D)	80	Wire Rope End	\boxtimes			
A - B30.5-1.7.4(b)	81	Wire Rope Retainer (Close Fitting Guards)	\boxtimes			
O - 1926.1412(f)(2)(iii)	82	Jib / Luffing / Tower & Lift Cylinder Pins			\boxtimes	
O - 1926.1412(f)(2)(I)	83	Sheave plate head section				
O - 1926.1412(f)(2)(i)(A)	84	Structure	\boxtimes			
		LOAD BLOCK & HOOK				
O - 1926.1433(d)(3)	85	Capacity marking	\boxtimes			
O - 1926.1433(d)(3)	86	Weight marking	\boxtimes			
O - 1926.1412(f)(2)(ii)	87	Sheave	\boxtimes			
A - B30.5-1.7.4(b)	88	Wire Rope Retainer (Close Fitting Guard)	\boxtimes		7 🗆	
O - 1926.1433(d)(4)	89	Safety Latching Mechanism	\boxtimes			
A - B30.10-1.10.5(f)	90	0° Hook Bend or Twist				
A - B30.10-1.10.5(g)	91	5% Hook Opening or 1/4" Max				
A - B30.10-1.10.5(e)	92	10% Hook Wear Max	\boxtimes			
O - 1926.1412(f)(2)(iii)	93	Hook Swivel/Bearing	\boxtimes			
O-B30.5-2.2.2		01 - LOAD TEST - MAIN BO	OM:			
Decree and like Langeth		50 FFFT Main Boom and No.				

O-B30.5-2.2.2	01 - LOAD TEST - MAIN BOOM:	
Boom and Jib Length	50 FEET Main Boom and No Jib	1
Load Radius	40 FEET	
Rated Capacity	8 TON	

SHORT BRIEF(COMMENTS) OF INSPECTION ACTIVITY WITH LOAD TEST

Thorough visual examination and Function Test on MOBILE CRANE.

Inspection result: Above mentioned equipment found satisfactory, We recommend for further use.

3



"Quality is our best priority"

A DIFE Enlisted Company

INSPECTION REPORT OF TRUCK MOUNTED CRANE – IQCERT505MLS02

Photographs During This Inspection









- 1. This is to certify that the equipment described in this certificate was inspected and tested in accordance to the aforementioned standard and regulations and at the time of inspection it was found free from serious defects and safe to use. We kindly advise to implement corrective action on the items mentioned in this report/certificates.
- 2. The Certificates validity cease in the event that any alternation, substantial repair and significant changes in design or construction of the equipment.
- 3. This certificate shall not be reproduced except in full without the approval of IQCert International Ltd & Client.
- 4. This certificate is **valid for 12 months** from the date of inspection.
- 5. All the information obtained/gathered during inspection shall be preserved as confidential.

Date of Inspection: 18 MARCH, 2023

Next Date of Inspection:

17 MARCH, 2024

Prepared By

Engr. Ahasan Ullah Hasan

Jam

Inspection Engineer IQCert International Ltd

Inspection & Authorization Engr. Kowshik Das

My

Inspection Consultant IQCert International

iornational Land



.....END OF REPORT.....

Registered Address: Plot # 87, BNS Center, Sector # 07, Uttara, Dhaka – 1230, Bangladesh
Operation Office: Plot # 03 (3rd Floor), Road # 16, Sector # 11, Uttara Model Town, Dhaka-1

Operation Office: Plot # 03 (3rd Floor), Road # 16, Sector # 11, Uttara Model Town, Dhaka-1230, Bangladesh. Mobile:+8801400-485888, +8801722283001 Email: operation@igcertinter.com Web: www.igcertinter.com